



WORKTOP JOINS

We always aim to minimise the numbers of joins required within worksurfaces. However, sometimes joins are simply unavoidable (eg. due to access restrictions).

The simple butt-joint is often the best solution but alternatives such as the GEC Anderson® clamp joint can sometimes be more appropriate where a mechanical connection is required.

Please speak to our technical department for guidance and advice:

Call us on +44 (0)1442 826999 or Email us info@gecanderson.co.uk
